

FUSION 360

Learning how to set up a tool path in Fusion



VOCABULARY

- Fusion 360
- Tool Path
- Tool Orientation
- Stock
- CNC Mill
- CNC Router
- RPM

NOTES:

FINISH YOUR PART IN INVENTOR


- After finishing your part in inventor save the .ipt
- Open Fusion 360
 - You will need to create an account using your STUDENT e-mail
 - If you do not create a STUDENT account your trial may end before you are done with the course.
- On the left hand side click the **Upload** button
 - Either **Select Files** or drag and drop your .ipt file into the uploader
 - Then hit upload
 - Then close the uploader
- You should now see your file on the left hand side
 - This is where all future files will be uploaded as well
 - Double click on the file you want to open

SETTING UP YOUR TOOL PATH

- In the tool bar click the first button on the left (might say sculpt) and change it to **MANUFACTURE**
- Change your units to Inches
- Click on New Set Up
- In order to select the correct orientation for the part and tool you will need to change to **Orientation** **Select Z axis/plane & X ax...**
 - Use the mouse to select the Z “edge” of your part (Height)
 - Then use the mouse to select the X “edge” of your part
 - You may need to “flip the x axis” or “flip the z axis”
 - Then select the “stock box point” so the machine has a place to start
 - Click on the bottom left front corner of your “stock” for (Brake Part), choose the center point for the (Maze)
 - It should look something like this
- Under the Stock Tab **Stock**
 - **OPTION 1:** Find **Mode** **Fixed size box**
 - Change the width, depth and height to the size of your material
 - Under the Height (Z) Model Position: Offset from bottom (-Z)
 - Offset: 0
 - You need to do this in order for your stock to cut to the bottom of the material
 - Click OK
 - **OPTION 2:** Find **Mode** **Relative size box**
 - Stock Top Offset: _____







2D/3D TOOL PATHS:

Do not be afraid to try different options for your project. The simulator will tell you if it will work correctly for you or not. There may be a faster option that will take less time or an option that will look better with your material.



OPTION 2 Equation:

$$\begin{aligned} &\text{Material Height} \quad \underline{\hspace{2cm}} \\ - &\text{Part Height} \quad \underline{\hspace{2cm}} \\ &= \underline{\hspace{2cm}} \end{aligned}$$


- Now we are going to set up the path the machine (tool) is going to follow
 - Click on the drop down  or 
 - Then depending on what you are working on select the tool path that will work best for your project
 - This is where you will set up your settings for the path
 - Click on Tool: Select 
 - Click on the new mill tool button  Type
 - Change the Type to Flat end mill 
 - Diameter: 0.25 in
 - Body Length: 2 in
 - Click on the **Feed & Speed** tab
 - These will depend on the machine (Mill or Router) and material you are using
 - Click OK and OK again
 - Under the Passes Tab 
 - Change your Max rough step down to .25"
 - Stock to leave: 0 (You do not want anything left)
 - Click OK
 - This will take a moment while it works on your tool path, you will start to see blue lines around your part
- If you go back and change any setting your might see an error on your tool path
 - Double click on it and hit OK again
 - This will re-run your path

BRAKE BRAKET

3D – Adaptive Clearing

MAZE


2D – Contour

-Geometry Tab 

-Select bottom of walls with

Contour Selections

-May need to set up tool again



MILL

FOAM:

Spindle Speed:5000rpm

ROUTER

FOAM:



Spindle Speed:10000rpm

Cutting Feed Rate: 200


2D/3D TOOL PATHS:

Do not be afraid to try different options for your project. The simulator will tell you if it will work correctly for you or not. There may be a faster option that will take less time or an option that will look better with your material.

SIMULATING THE TOOL PATH

- Now that everything is set up we need to check if your tool path is correct and will work
- Make sure you have your [T1]Adaptive selected then click Simulate 
 - Uncheck Tool Path
 - Check “Stock”
 - This will allow you to see the material being cut away
 - Then click on the Play Button 
 - You can use the slider to speed it up
 - Under the Info Tab you can check the “time” it is going to take

SAVING YOUR FILE FOR THE MACHINE (MILL/ROUTER)

- The machines speak a different language called G-Code
- Click on the 
- Post Configuration - **Router:** Forest Scientific **Mill:** Tormach Path Pilot
- Output folder – to your H:drive or Flash Drive (you will need it on your flash drive for the machine)
- Post
- Change the file name to LAST NAME PART NAME and save
 - You can close out of the code window that comes up